	Туре	L #	Hits	Search Text	DBs
1	IS&R	L1	1332	(606/61).CCLS.	USPAT
2	BRS	L2	218	ll and (bushing or washer)	USPAT
3	BRS	L3	0	l2 and elastic\$2 near (pin or screw)	USPAT
4	BRS	L4	1	l2 and spring near (pin or screw)	USPAT
5	BRS	L5	12	12 and screw near lock	USPAT
6	BRS	L6	10	("5470333" "6176861").PN. OR ("6235033").URPN.	US- PGPUB ; USPAT ; USOCR
7	BRS	L 7	363	plate and washer and bushing and screw near lock	US- PGPUB ; USPAT ; USOCR
8	BRS	L8	6	17 and (elastic or spring)near loaded near (screw or pin)	US- PGPUB ; USPAT ; USOCR
9	BRS	L9	7	("5489210" "5569251" "5713900" "5843082" "6036693" "6168597" "6235033").PN. OR ("6613053").URPN.	US- PGPUB ; USPAT ; USOCR

7					US- PGPUB
10	BRS	11.10	screw and ba prevent\$3	ack near ou	t ; USPAT
			-		; USOCR

r	Time Stamp	Comments	Error Definition	Err
1	2005/01/26 15:31			
2	2005/01/26 15:34		_	
3	2005/01/26 15:33			
4	2005/01/26 15:33			
5	2005/01/26 15:35			
6	2005/01/26 15:38			
7	2005/01/26 15:39			
8	2005/01/26 15:39			·
9	2005/01/26 15:45		·	
10	2005/01/26 15:45		·	

	Туре	L #	Hits	Search Text	DBs
11	BRS	L11	34	screw and back near out near prevent\$3	US- PGPUB ; USPAT ; USOCR
12	BRS	L12	23	thramann.in.	US- PGPUB; USPAT; USOCR; EPO; DERWE NT; IBM_T DB
13	BRS	L13	13956	(fulton or hildebrand or powell).in.	US- PGPUB; USPAT; USOCR; EPO; JPO; DERWE NT; IBM_T DB

•	Time	Stamp	Comments	Error Definition	Err
11	2005/ 15:49	'01/26)			
12	2005/ 15:53	'01/26 3			
13	2005/ 15:53	/01/26 3			

•	Туре	L #	Hits	Search Text	DBs
14	BRS	L14	1/1 × 1	l13 and (bushing or washer)	US- PGPUB; USPAT; USOCR; EPO; DERWE NT; IBM_T DB
15	BRS	L15	6	l14 and ((back near out near prevent\$4) or (screw near lock))	US- PGPUB; USPAT; USOCR; EPO; DERWE NT; IBM_T DB

	Time	Stamp	Comments	Error Definition	Err
14	2005/ 15:54	01/26		-	
15	2005/ 15:55	'01/26 5			